
New Shamir Relax™

Product Availability and Markings

Material	Index	Power Range	Nominal Base Curve*	Add	Color	Fitting Height	Invisible Marking	
Hard Resin	1.498	-14.00 to +8.00	0.5, 2, 3, 4, 5, 6, 7, 8, 9	0.75 to 3.50	Clear	14mm	15 S RLX 5	\$
Blue Zero	1.498	-14.00 to +8.00	0.5, 2, 3, 4, 5, 6, 7, 8, 9	0.75 to 3.50	Clear	14mm	BS5 S RLX 5	\$
Polarized	1.498	-14.00 to +8.00	0.5, 2, 3, 4, 5, 6, 7, 8, 9	0.75 to 3.50	Clear	14mm	PZ S RLX 5	\$
Transitions® Signature®	1.5	-14.00 to +8.00	0.5, 2, 3, 4, 5, 6, 7, 8, 9	0.75 to 3.50	Gray, Brown & Green	14mm	TR S RLX 5	\$
Transitions® XTRActive®	1.5	-14.00 to +8.00	0.5, 2, 3, 4, 5, 6, 7, 8, 9	0.75 to 3.50	Gray & Brown	14mm	X5 S RLX 5	\$
Transitions® Drivewear®	1.5	-14.00 to +8.00	0.5, 2, 3, 4, 5, 6, 7, 8, 9	0.75 to 3.50	Drivewear®	14mm	DW S RLX 5	\$
DLC™ (Trivex)	1.53	-14.00 to +8.00	0.5, 2, 3, 4, 5, 6, 7, 8, 9	0.75 to 3.50	Clear	14mm	TX S RLX 5	S
DLC™ (Trivex) Blue Zero	1.53	-14.00 to +8.00	0.5, 2, 3, 4, 5, 6, 7, 8, 9	0.75 to 3.50	Clear	14mm	BZX S RLX 5	S
DLC™ (Trivex) Polarized	1.53	-14.00 to +8.00	0.5, 2, 3, 4, 5, 6, 7, 8, 9	0.75 to 3.50	Clear	14mm	PTX S RLX 5	\$
DLC™ (Trivex) Transitions® Signature®	1.53	-14.00 to +8.00	0.5, 2, 3, 4, 5, 6, 7, 8, 9	0.75 to 3.50	Gray, Brown & Green	14mm	TTX S RLX 5	S
DLC™ (Trivex) Transitions® XTRActive®	1.53	-14.00 to +8.00	0.5, 2, 3, 4, 5, 6, 7, 8, 9	0.75 to 3.50	Gray & Brown	14mm	XX S RLX 5	\$
1.56	1.56	-14.00 to +8.50	0.5, 2, 3, 4, 5, 6, 7, 8, 9	0.75 to 3.50	Clear	14mm	56 S RLX 5	\$

^{*} The true base curve can be selected from a range of curves that has been defined in the Freeform Software.




New Shamir Relax™

Product Availability and Markings

Material	Index	Power Range	Nominal Base Curve*	Add	Color	Fitting Height	Invisible Marking	
Polycarbonate	1.586	-14.00 to +8.75	0.5, 2, 3, 4, 5, 6, 7, 8	0.75 to 3.50	Clear	14mm	PC S RLX 5	\$
Polycarbonate Blue Zero	1.586	-14.00 to +8.75	0.5, 2, 3, 4, 5, 6, 7, 8	0.75 to 3.50	Clear	14mm	BZP S RLX 5	\$
Polycarbonate Polarized	1.586	-14.00 to +8.75	0.5, 2, 3, 4, 5, 6, 7, 8	0.75 to 3.50	Clear	14mm	PPZ S RLX 5	\$
Polycarbonate Transitions® Signature®	1.586	-14.00 to +8.75	0.5, 2, 3, 4, 5, 6, 7, 8	0.75 to 3.50	Gray, Brown & Green	14mm	PT S RLX 5	\$
Polycarbonate Transitions® XTRActive®	1.586	-14.00 to +8.75	0.5, 2, 3, 4, 5, 6, 7, 8	0.75 to 3.50	Gray & Brown	14mm	PX S RLX 5	S
Polycarbonate Transitions® Drivewear®	1.586	-14.00 to +8.75	0.5, 2, 3, 4, 5, 6, 7, 8	0.75 to 3.50	Drivewear®	14mm	PD S RLX 5	\$
SuperLite™ 1.6	1.6	-14.00 to +8.75	0.5, 2, 3, 4, 5, 6, 7, 8	0.75 to 3.50	Clear	14mm	16 S RLX 5	\$
SuperLite Blue Zero 1.6	1.6	-14.00 to +8.75	0.5, 2, 3, 4, 5, 6, 7, 8	0.75 to 3.50	Clear	14mm	BZ6 S RLX 5	\$
SuperLite 1.6 Polarized	1.6	-14.00 to +8.75	0.5, 2, 3, 4, 5, 6, 7, 8	0.75 to 3.50	Clear	14mm	PZ6 S RLX 5	\$
SuperLite 1.6 Transitions® Signature®	1.6	-14.00 to +8.75	0.5, 2, 3, 4, 5, 6, 7, 8	0.75 to 3.50	Gray, Brown & Green	14mm	T6 S RLX 5	S
SuperLite 1.6 Transitions® XTRActive®	1.6	-14.00 to +8.75	0.5, 2, 3, 4, 5, 6, 7, 8	0.75 to 3.50	Gray & Brown	14mm	X6 S RLX 5	\$
SuperLite 1.67	1.67	-16.00 to +16.00	0.5, 2, 3, 4, 5, 6, 7, 8, 9.5,11,12.5	0.75 to 3.50	Clear	14mm	67 S RLX 5	\$

^{*} The true base curve can be selected from a range of curves that has been defined in the Freeform Software.



New Shamir Relax™

Product Availability and Markings

Material	Index	Power Range	Nominal Base Curve*	Add	Color	Fitting Height	Invisible Marking	
SuperLite Blue Zero 1.67	1.67	-16.00 to +16.00	0.5, 2, 3, 4, 5, 6, 7, 8, 9.5,11,12.5	0.75 to 3.50	Clear	14mm	BZ67 S RLX 5	8
SuperLite 1.67 Polarized	1.67	-16.00 to +16.00	0.5, 2, 3, 4, 5, 6, 7, 8, 9.5,11,12.5	0.75 to 3.50	Clear	14mm	PZ67 S RLX 5	\$
SuperLite 1.67 Transitions® Signature®	1.67	-16.00 to +16.00	0.5, 2, 3, 4, 5, 6, 7, 8, 9.5,11,12.5	0.75 to 3.50	Gray, Brown & Green	14mm	T67 © RLX 5	\$
SuperLite 1.67 Transitions® XTRActive®	1.67	-16.00 to +16.00	0.5, 2, 3, 4, 5, 6, 7, 8, 9.5,11,12.5	0.75 to 3.50	Gray & Brown	14mm	X67 S RLX 5	\$
SuperLite 1.74	1.74	-20.00 to +16.75	0.5, 1, 1.5, 2.5, 3.5, 4.75, 6, 7, 8, 9, 9.75, 10.5, 11.25, 12	0.75 to 3.50	Clear	14mm	74 ⑤ RLX 5	\$
SuperLite 1.74 Transitions® Signature®	1.74	-20.00 to +16.75	0.5, 1, 1.5, 2.5, 3.5, 4.75, 6, 7, 8, 9, 9.75, 10.5, 11.25, 12	0.75 to 3.50	Gray & Brown	14mm	T74	\$

^{*} The true base curve can be selected from a range of curves that has been defined in the Freeform Software.

